

Mercedes-Benz rappelle EQV, Sprinter, eSprinter, eVito, Vito, V-Class Camionnette/Véhicule utilitaire léger

Image non disponible

- EQV, Sprinter, eSprinter, eVito, Vito, V-Class Camionnette/Véhicule utilitaire léger
- Marque : Mercedes-Benz
- GTIN The affected vehicles were manufactured between 12 August 2013 and 22 February 2021
- Informations complémentaires : 639/2, 639/2, 639/2, 639/4, 639/4, 639/5, KL3A4, FL3A4, KL3A5, KL3A5, FL3A5 , Types: 906 AC 35, 906 AC 35, 906 AC 35/4x4, 906BA50, 906BB50, 906BA35, 906BB35, 906BB50/4x4, 906BB35/4x4, 906BA50/4x4, 906BA35/4x4, , e1*2001/116*0354*17, e1*2001/116*0354*21-*26, e1*2001/116*0424*15-*17, e1*2007/46*0294*10-*14, e1*2007/46*0296*10-*14, e1*2007/46*0300*15-*19, e1*2007/46*0301*17-*21, e1*2007/46*0304*06-*08, , e1*2007/46*0305*11-*13, e1*2007/46*0308*06-*08, e1*2007/46*0312*12-*14, e1*2007/46*0457*11, e1*2007/46*0457*13-*14, e1*2007/46*0457*16-*26, e1*2007/46*0458*12, e1*2007/46*0458*13-*20,, e1*2007/46*0459*08-*13, e1*2007/46*1760*00-*04, e1*2007/46*1761*00-*04, e1*2007/46*1762*00-*02, e1*2007/46*1762*04, e1*2007/46*1763*00-*04

POURQUOI CE PRODUIT EST-IL DANGEREUX ?

- Motif du rappel : Le fonctionnement du système d'appel d'urgence peut dans certains cas être compromis. Le logiciel du module de communication sera mis à jour sur les véhicules concernés.
- Risques encourus par le consommateur : Blessures

QUE FAIRE ?

- Conduite à tenir par le consommateur : **contacter le concessionnaire.**

Retrouvez toutes les informations sur les rappels de produits sur le site:

<https://rappel.conso.gouv.fr>

Le site des alertes de produits dangereux



FAITES PASSER LE MESSAGE :

Informez vos parents et amis de ce rappel !

Faites circuler l'information au sujet de ce rappel, surtout si vous savez que le produit faisant l'objet du rappel a été offert, prêté ou vendu à quelqu'un d'autre