

**Ford rappelle Transit Connect, Focus, Ecosport Voiture particulière sous le code de rappel Ford: 20S05.**

Image non disponible

- Transit Connect, Focus, Ecosport Voiture particulière sous le code de rappel Ford: 20S05.
- Marque : Ford
- GTIN The affected vehicles were manufactured between 14 and 28 January 2020 (Focus), between 14 and 27 January 2020 (Ecosport), between 22 and 26 January 2020 (Transit Connect)
- Informations complémentaires : Type-approval numbers: e1\*2007/46\*0272\*22, e13\*2007/46\*1911\*06, e9\*2007/46\*0092\*29

#### **POURQUOI CE PRODUIT EST-IL DANGEREUX ?**

- Motif du rappel : En raison d'un problème de fabrication, l'amplificateur de frein peut être assemblé avec trop de pression appliquée à la plaque de diaphragme. Par conséquent, la plaque de diaphragme peut se fissurer, provoquant la rupture de la membrane interne. Cela entraînera une perte soudaine de l'efficacité des freins, ce qui augmentera le risque d'accident.
- Risques encourus par le consommateur : Blessures

#### **QUE FAIRE ?**

- Conduite à tenir par le consommateur : **contacter le concessionnaire.**

**Retrouvez toutes les informations sur les rappels de produits sur le site:**

**<https://rappel.conso.gouv.fr>**

Le site des alertes de produits dangereux



**FAITES PASSER LE MESSAGE :**

Informez vos parents et amis de ce rappel !

Faites circuler l'information au sujet de ce rappel, surtout si vous savez que le produit faisant l'objet du rappel a été offert, prêté ou vendu à quelqu'un d'autre