

Peugeot rappelle 308 - 3008 - 5008 - Traveller/expert Voiture de tourisme

Image non disponible

- 308 - 3008 - 5008 - Traveller/expert Voiture de tourisme
- Marque : Peugeot
- GTIN 3008: manufactured between 27 April 2018 and 30 May 2018 VIN: VF3MJAHWWJS184411 to VF3MJAHXVKS007901 308: manufactured between 27 April 2018 and 30 May 2018 VIN: VF3LHAHXWJS210762 to VF3LJEHZRJS259159 5008: manufactured between 26 April 2018 and 2 June 2018 VIN: VF3MJAHXHJL034823 to VF3MJAHWWKL003025 Traveller/Expert: manufactured between 30 April 2018 and 31 May 2018 VIN: VF3VEAHHWJZ043136 to VF3VFAHXGKZ001117
- Informations complémentaires : 3008 : e2*2007/46*0534*04, e2*2007/46*0534*05 308 : e2*2007/46*405*17, e2*2007/46*0405*18, 5008 : e2*2007/46*0534*04, e2*2007/46*0534*05 Traveller/expert : e2*2007/46*0532*04, e2*2007/46*0532*05, e2*2007/46*0533*04

POURQUOI CE PRODUIT EST-IL DANGEREUX ?

- Motif du rappel : Il se peut que le bouchon de la galerie d'huile du cylindre-logement n'ait pas été correctement serré.
- Risques encourus par le consommateur : Blessures

QUE FAIRE ?

- Conduite à tenir par le consommateur : **contacter le concessionnaire.**

Retrouvez toutes les informations sur les rappels de produits sur le site:

<https://rappel.conso.gov.fr>

Le site des alertes de produits dangereux



FAITES PASSER LE MESSAGE :

Informez vos parents et amis de ce rappel !

Faites circuler l'information au sujet de ce rappel, surtout si vous savez que le produit faisant l'objet du rappel a été offert, prêté ou vendu à quelqu'un d'autre