

Mazda rappelle 3, 6, CX-5 Voiture particulière sous le code de rappel Mazda: AK038A.

Image non disponible

- 3, 6, CX-5 Voiture particulière sous le code de rappel Mazda: AK038A.
- Marque : Mazda
- GTIN The affected vehicles were manufactured between 7 November 2018 and 13 May 2019 (Mazda 3), between 26 March 2018 and 22 April 2019 (Mazda 6), between 20 June 2017 and 20 April 2019 (Mazda CX-5).
- Informations complémentaires : Mazda 3 (BP), Mazda 6 (GL), CX-5 (KF)

POURQUOI CE PRODUIT EST-IL DANGEREUX ?

- Motif du rappel : En raison d'une erreur logicielle, le module de commande du groupe motopropulseur (PCM) peut fonctionner mal en passant des modes de désactivation du cylindre à l'activation complète du cylindre. Par conséquent, un bras à bascule de soupape d'admission peut sortir de sa position et entrer en contact avec des pièces internes du moteur.
- Risques encourus par le consommateur : Blessures

QUE FAIRE ?

- Conduite à tenir par le consommateur : **contacter le concessionnaire.**

Retrouvez toutes les informations sur les rappels de produits sur le site:

<https://rappel.conso.gouv.fr>

Le site des alertes de produits dangereux



FAITES PASSER LE MESSAGE :

Informez vos parents et amis de ce rappel !

Faites circuler l'information au sujet de ce rappel, surtout si vous savez que le produit faisant l'objet du rappel a été offert, prêté ou vendu à quelqu'un d'autre